

**Flood Control Project Maintenance
Levee Inspections**

Fall 2016 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including USACE Erosion Survey

Sacramento River Basin

RD0784	Overall LMA Rating	Total LMA Miles						
Reclamation District No. 0784 Plumas Lake	A	33.20						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Encroachments					2.89			
<i>Supplemental</i>								
DWR UCIP Field Study					0.11	0.01		
<i>LMA Totals:</i>	0.00	0.00	0.00	0.00%	3.00	0.01	0.00	0.00

Unit No. 01 Yuba River LB	Overall Unit Rating	Total Unit Miles						
RD0784	A	2.21						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Encroachments					0.61			
<i>Supplemental</i>								
DWR UCIP Field Study					0.01			
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.62	0.00	0.00	0.00

Unit No. 02A Feather River LB	Overall Unit Rating	Total Unit Miles						
RD0784	A	2.54						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
No Items								
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%				

Unit No. 02B Feather River LB	Overall Unit Rating	Total Unit Miles						
RD0784	A	3.95						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Encroachments					0.10			
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.10	0.00	0.00	0.00

Unit No. 03A Bear River RB	Overall Unit Rating	Total Unit Miles						
RD0784	A	0.78						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
No Items								
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%				

**Flood Control Project Maintenance
Levee Inspections**

Fall 2016 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 03B Bear River RB	Overall Unit Rating	Total Unit Miles						
RD0784	A	1.49						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Supplemental</i>								
DWR UCIP Field Study					0.01			
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.01	0.00	0.00	0.00
Unit No. 04 Interceptor Canal RB	Overall Unit Rating	Total Unit Miles						
RD0784	A	6.33						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Supplemental</i>								
DWR UCIP Field Study					0.01			
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.01	0.00	0.00	0.00
Unit No. 05 Interceptor Canal LB	Overall Unit Rating	Total Unit Miles						
RD0784	A	4.19						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Encroachments					2.18			
<i>Supplemental</i>								
DWR UCIP Field Study					0.05	0.01		
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	2.23	0.01	0.00	0.00
Unit No. 06 South Dry Creek RB	Overall Unit Rating	Total Unit Miles						
RD0784	A	0.25						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Supplemental</i>								
DWR UCIP Field Study					0.01			
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.01	0.00	0.00	0.00
Unit No. 07 Yuba River LB	Overall Unit Rating	Total Unit Miles						
RD0784	A	3.82						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
No Items								
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%				
Unit No. 08 Three Rivers RB	Overall Unit Rating	Total Unit Miles						
RD0784	A	1.93						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
No Items								
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%				

**Flood Control Project Maintenance
Levee Inspections**

Fall 2016 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including USACE Erosion Survey

Sacramento River Basin (cont.)

Unit No. 09 Feather River LB		Overall Unit Rating	Total Unit Miles						
RD0784		A	5.71						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence		
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles	
<i>Supplemental</i>									
DWR UCIP Field Study					0.02				
<i>Unit Totals:</i>	0.00	0.00	0.00	0.00%	0.02	0.00	0.00	0.00	

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Fall 2016 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
† Overall LMA Rating (Fall Only)			A	

** Non-receipt of Summer or Winter Inspection
Reports may effect overall annual rating.

† **SPRING INSPECTIONS:** Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2016 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway			Bank	Unit Miles
Unit No. 01 Yuba River			Left	2.21
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/22/2016 - 3/22/2016		11/1/2016 - 11/1/2016	
DWR Inspector	Sterling York		Sterling York	
Accompanied By				

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yuba River	Left	2.21	11/01/2016 11/01/2016	Sterling York

LM Start	0.00	Rating **	A	Issue No.	4
LM End	0.00	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_RD0784_01_s_2013_4				
Comment Code					
Inspector Comment					
O&M manuals are located at the district office.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	5
LM End	0.00	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_RD0784_01_s_2013_5				
Comment Code					
Inspector Comment					
RD 784 participates with the neighboring districts to strategically place flood fight supplies around the local districts for fast response. They also have a shipping container at their district office, and three containers at another district full of flood fight supplies.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	6
LM End	0.00	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_RD0784_01_s_2013_6				
Comment Code					
Inspector Comment					
RD 784 and its employees host and participate in a Flood Fight class put on by DWR every fall in their district.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yuba River	Left	2.21	11/01/2016 11/01/2016	Sterling York

LM Start	0.04	Rating **	A	Issue No.	2
LM End	2.20	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.134450 °	39.125874 °
				-121.552671 °	-121.588644 °
DWR ID	DWR_RD0784_01_f_2016_2				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_178_2_20161103_00006.jpg



View of waterside looking downstream of well maintained annual vegetation. Fall 2016.

LM Start	0.04	Rating **	A	Issue No.	3
LM End	2.20	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.134450 °	39.125874 °
				-121.552672 °	-121.588644 °
DWR ID	DWR_RD0784_01_f_2016_3				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_178_3_20161103_00007.jpg



View of landside looking downstream of well maintained annual vegetation. Fall 2016.

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yuba River	Left	2.21	11/01/2016 11/01/2016	Sterling York

LM Start	0.51	Rating **	M	Issue No.	12
LM End	1.00	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.131558 °	39.129475 °
				-121.560668 °	-121.569209 °
DWR ID	DWR_RD0784_01_f_2012_12				
Comment Code					
FE : Fence					
Inspector Comment					
Fences are found within the 10 feet of levee easement .					

Photo 1 of 1 : FA_2016_RD0784_178_12_20161103_00008.jpg



Fences were found on the landside toe of the levee looking downstream. Fall 2016.

LM Start	1.00	Rating **	M	Issue No.	13
LM End	1.12	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.129475 °	39.129615 °
				-121.569210 °	-121.571371 °
DWR ID	DWR_RD0784_01_f_2012_13				
Comment Code					
FE : Fence					
Inspector Comment					
Fence near the levee toe. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_178_13_20161103_00009.jpg



This photo shows a fence near the levee toe on the landside looking downstream. Fall 2016.

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yuba River	Left	2.21	11/01/2016 11/01/2016	Sterling York

LM Start	1.31	Rating **	M	Issue No.	14
LM End	1.31	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.129826 °	39.129826 °
				-121.574940 °	-121.574940 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:50677
DS_ID:18552
EP_NO: N/A
Repair Type: Non-Urgent
Crossing Status: Indicator Found
UCIP Comments: 11/15/2016 - Crossing is still Non-Urgent due to the possibility that the pipe is unpermitted. The crossing will be downgraded when owner provides permit or CVFPB enforcement resolves the issue. (DWR UCIP - thatch)11/01/2015 - Letter requesting permit or to provide permit sent to owner Century Link, 700 W. Mineral Avenue, Rm D 27.34, Littleton, CO 80120 on 2/18/2014. Pending CVFPB enforcement on utility crossing owner. Requesting DWR inspector to change the status of this issue to "No Action Needed" (P. Meagher - RD784) 02/28/2013 - No permit identified for this crossing. Need to determine if owner has permit. (W.Wylie UCIP Inspector).
FIELD_STRUCT_DESC: Fiber Optic Communication lines cross levee. Diameter unknown.
FS Date: 9/11/2015 9:08:00 AM

LM Start	1.31	Rating **	M	Issue No.	14 (cont)
LM End	1.31	Issue Type +	En	Location *	LS

Photo 1 of 2 : UCIP_FA_2016_50677_54402.jpg



Marker on east side of Rail/WS of Levee.

Photo 2 of 2 : UCIP_FA_2016_50677_54401.jpg



Marker on east side of Rail/WS of Levee.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2016 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway			Bank	Unit Miles
Unit No. 02A Feather River			Left	2.54
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/22/2016 - 3/22/2016		11/1/2016 - 11/1/2016	
DWR Inspector	Sterling York		Sterling York	
Accompanied By	Patrick Meagher RD 784		Patrick Meagher RD 784	

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02A Feather River	Left	2.54	11/01/2016 11/01/2016	Sterling York

LM Start	0.01	Rating **	A	Issue No.	1
LM End	2.53	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.125763 °	39.090425 °
				-121.588667 °	-121.584694 °
DWR ID	DWR_RD0784_02A_f_2016_1				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 2 : FA_2016_RD0784_531_1_20161103_00005.jpg



First view looking downstream of landside well maintained annual vegetation. Fall 2016.

LM Start	0.01	Rating **	A	Issue No.	1 (cont)
LM End	2.53	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : FA_2016_RD0784_531_1_20161117_00007.jpg



Second view looking downstream on waterside of well maintained annual vegetation. Fall 2016.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02A Feather River	Left	2.54	11/01/2016 11/01/2016	Sterling York

LM Start	0.01	Rating **	A	Issue No.	2
LM End	2.53	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.125763 °	39.090425 °
				-121.588667 °	-121.584695 °
DWR ID	DWR_RD0784_02A_f _ 2016_2				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 2 : FA_2016_RD0784_531_2_20161103_00003.jpg



First view of waterside looking downstream of well maintained annual vegetation. Fall 2016.

LM Start	0.01	Rating **	A	Issue No.	2 (cont)
LM End	2.53	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : FA_2016_RD0784_531_2_20161103_00004.jpg



Second view of waterside looking downstream of well maintained annual vegetation. Fall 2016.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2016 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway			Bank	Unit Miles
Unit No. 02B Feather River			Left	3.95
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/22/2016 - 3/22/2016		11/1/2016 - 11/1/2016	
DWR Inspector	Sterling York		Sterling York	
Accompanied By	Patrick Meagher RD 784		Patrick Meagher RD 784	

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02B Feather River	Left	3.95	11/01/2016 11/01/2016	Sterling York

LM Start	8.96	Rating **	A/W	Issue No.	1
LM End	9.36	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			39.009366 °	39.004549 °
				-121.579766 °	-121.579143 °
DWR ID	DWR_RD0784_02B_f _ 2015_1				
Comment Code					
Inspector Comment					
2003 - Bank is near vertical. Identified as a Potentially Critical site. 2004 - Eddy flow off downstream end of Modesto formation eroding the fluvial sediments. 2005 - Some new slumping. Actively eroding but berm width is greater than 50 ft. 2006 - Downgraded to regular erosion site. Still actively eroding. Large old rotational failures in high bank on the downstream end. 2008 - Removed from inventory due to wide berm width does not meet criteria for an erosion site. 2010 - Added back to the inventory after 10 ft of bank erosion in the winter 2009 storm. Steep vertical face. 2011 - Bank has retreated an additional 2.5 ft from last year. New tree popouts and erosion throughout the site. 2012 - Site continues to worsen with new tree popouts and many sections of new erosion. 2015: Last observed in 2013. [2015 Site ID: FHR_17-8_L]					

Photo 1 of 1 : FA_2016_RD0784_532_1_20160906_00001.jpg



USACE 2013 Photo #1

LM Start	9.00	Rating **	A	Issue No.	4
LM End	12.80	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.009547 °	38.955539 °
				-121.578826 °	-121.574624 °
DWR ID	DWR_RD0784_02B_f_2016_4				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_532_4_20161103_00006.jpg



Second view of waterside looking downstream at well maintained annual vegetation. Fall 2016.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02B Feather River	Left	3.95	11/01/2016 11/01/2016	Sterling York

LM Start	9.00	Rating **	A	Issue No.	3
LM End	12.80	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.009547 °	38.955539 °
				-121.578825 °	-121.574623 °
DWR ID	DWR_RD0784_02B_f_2016_3				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_532_3_20161103_00007.jpg



View of landside looking downstream of landside well maintained annual vegetation. Fall 2016.

LM Start	9.21	Rating **	M	Issue No.	6
LM End	9.31	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.006523 °	39.005235 °
				-121.577843 °	-121.578286 °
DWR ID	DWR_RD0784_02_f_2012_6				
Comment Code					
MA : Material					
Inspector Comment					
Un-permitted paving at levee toe. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_532_6_20161103_00008.jpg



View looking downstream on the land side of un-permitted paving. Fall 2016.

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2016 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway			Bank	Unit Miles
Unit No. 03A Bear River			Right	0.78
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/22/2016 - 3/22/2016		11/1/2016 - 11/1/2016	
DWR Inspector	Sterling York		Sterling York	
Accompanied By	Patrick Meagher RD 784		Patrick Meagher RD 784	

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03A Bear River	Right	0.78	11/01/2016 11/01/2016	Sterling York

LM Start	2.43	Rating **	A	Issue No.	3
LM End	3.20	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.970576 °	38.974682 °
				-121.547586 °	-121.535308 °
DWR ID	DWR_RD0784_03A_f _ 2016_3				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_533_3_20161103_00002.jpg



View of waterside looking upstream at well maintained annual vegetation. Fall 2016.

LM Start	2.43	Rating **	A	Issue No.	1
LM End	3.20	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.970576 °	38.974682 °
				-121.547585 °	-121.535308 °
DWR ID	DWR_RD0784_03A_f_2016_1				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_533_1_20161103_00003.jpg



View of landside looking upstream of landside well maintained annual vegetation. Fall 2016.

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2016 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway			Bank	Unit Miles
Unit No. 03B Bear River			Right	1.49
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/23/2016 - 3/23/2016		11/1/2016 - 11/1/2016	
DWR Inspector	Sterling York		Sterling York	
Accompanied By	Patrick Meagher RD 784		Patrick Meagher RD 784	

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03B Bear River	Right	1.49	11/01/2016 11/01/2016	Sterling York

LM Start	3.22	Rating **	A	Issue No.	3
LM End	4.69	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.974438 °	38.985464 °
				-121.532366 °	-121.510722 °
DWR ID	DWR_RD0784_03B_f_2016_3				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_534_3_20161103_00001.jpg



View of landside looking upstream of landside well maintained annual vegetation. Fall 2016.

LM Start	3.22	Rating **	A	Issue No.	2
LM End	4.69	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.974438 °	38.985465 °
				-121.532366 °	-121.510722 °
DWR ID	DWR_RD0784_03B_f_2016_2				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_534_2_20161103_00002.jpg



View of waterside looking upstream at well maintained annual vegetation. Fall 2016.

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03B Bear River	Right	1.49	11/01/2016 11/01/2016	Sterling York

LM Start	4.66	Rating **	M	Issue No.	4
LM End	4.66	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.985247 °	38.985247 °
				-121.511075 °	-121.511075 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:50165
DS_ID:18627
EP_NO: N/A
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: 09/22/2016 - vegetation at inlet of pipe has been cleared by owner. photos added showing pipe inlet. (T.
Hatch/UCIP)08/09/2016 - vegetation partially obscuring outlet on WS.
Heavy vegetation on landside (LS) limiting inspection of inlet. Owner asked by RD0784 to clear vegetation and debris. (T.
Hatch/UCIP)11/1/2015 - Flap Gate has been cleared as of 12/9/2014 and again during summer of 2015 (P. Meagher/RD0784)2/27/2013 - Flap gate blocked by vegetation on WS toe. Unable to locate inlet. (W. Wylie/UCIP)
FIELD_STRUCT_DESC: 18-inch corrugated metal drainage pipe through the levee, 20-feet below the crown. A gate valve is on the waterside (WS). {Additional Reference(s): USACE Sacramento O&M Manual 145, August 1955 (sta 4+96). USACE Sacramento As-built Drawings, 2-4-106, Exhibit B, Sheet 2, July 1944 (sta 4+96)].
FS Date: 9/21/2016

LM Start	4.66	Rating **	M	Issue No.	4 (cont)
LM End	4.66	Issue Type +	En	Location *	WS

Photo 1 of 2 : UCIP_FA_2016_50165_54225.jpg



Flap gate blocked by vegetation on WS Toe.

Photo 2 of 2 : UCIP_FA_2016_50165_54224.jpg



Flap gate blocked by vegetation on WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2016 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway			Bank	Unit Miles
Unit No. 04 Interceptor Canal			Right	6.33
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/22/2016 - 3/22/2016		11/1/2016 - 11/1/2016	
DWR Inspector	Sterling York		Sterling York	
Accompanied By				

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

Reclamation District No. 0784 Plumas Lake

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Interceptor Canal	Right	6.33	11/01/2016 11/01/2016	Sterling York

LM Start	3.59	Rating **	M	Issue No.	6
LM End	3.59	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.026347 °	39.026347 °
				-121.542343 °	-121.542343 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:46600 DS_ID:22686 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: No permit identified for crossing. FIELD_STRUCT_DESC: Communication line through the levee at unknown depth on downstream side of bridge. FS Date: 9/11/2015 9:25:57 AM					

LM Start	3.59	Rating **	M	Issue No.	6 (cont)
LM End	3.59	Issue Type +	En	Location *	WS

Photo 1 of 2 : UCIP_FA_2016_46600_54244.jpg



Communication line at base of JP on WS slope.

Photo 2 of 2 : UCIP_FA_2016_46600_54243.jpg



Communication line runs on south side of Plumas Arboga Road to JP approximately 400-feet West of levee crown.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Interceptor Canal	Right	6.33	11/01/2016 11/01/2016	Sterling York

LM Start	3.60	Rating **	A	Issue No.	5
LM End	5.84	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.026503 °	39.058462 °
				-121.542349 °	-121.543125 °
DWR ID	DWR_RD0784_04_f_2016_5				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
This section of levee on the landside is under construction with Permit Number 19020-1 to construct a stability berm and all weather access road. Fall 2016.					

Photo 1 of 2 : FA_2016_RD0784_181_5_20161103_00009.jpg



View of landside looking upstream. This section of levee on the landside is under construction with Permit Number 19020-1 to construct a stability berm and all weather access road. Fall 2016.

LM Start	3.60	Rating **	A	Issue No.	5 (cont)
LM End	5.84	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : FA_2016_RD0784_181_5_20161103_00010.jpg



Second view of landside looking upstream. This section of levee on the landside is under construction with Permit Number 19020-1 to construct a stability berm and all weather access road. Fall 2016.

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2016 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway			Bank	Unit Miles
Unit No. 05 Interceptor Canal			Left	4.19
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/23/2016 - 3/23/2016		11/1/2016 - 11/1/2016	
DWR Inspector	Sterling York		Sterling York	
Accompanied By	Patrick Meagher RD 784		Patrick Meagher RD 784	

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

Reclamation District No. 0784 Plumas Lake

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Interceptor Canal	Left	4.19	11/01/2016 11/01/2016	Sterling York

LM Start	0.84	Rating **	M	Issue No.	13
LM End	0.84	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.986432 °	38.986432 °
				-121.534983 °	-121.534983 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:46592
DS_ID:18591
EP_NO: N/A
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: No handle or access to slide gate on LS toe.
FIELD_STRUCT_DESC: 30-inch CM pipe through the levee 23.7 feet below the crown. Flap gate on the waterward end. Slide gate in concrete drop inlet on the landward side. Originally included in O+M manual (1955).
FS Date: 9/11/2015 9:05:55 AM

LM Start	0.84	Rating **	M	Issue No.	13 (cont)
LM End	0.84	Issue Type +	En	Location *	WS

Photo 1 of 2 : UCIP_FA_2016_46592_54246.jpg



Concrete drop-inlet at LS toe.

Photo 2 of 2 : UCIP_FA_2016_46592_54245.jpg



Outlet with riprap on WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Interceptor Canal	Left	4.19	11/01/2016 11/01/2016	Sterling York

LM Start	1.09	Rating **	M	Issue No.	10
LM End	1.72	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			38.989955 °	38.999068 °
				-121.535672 °	-121.537462 °
DWR ID	DWR_RD0784_05_s_2012_10				
Comment Code					
DT : Ditch					
Inspector Comment					
Ditch at toe of slope. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_182_10_20161103_00024.jpg



View of landside looking downstream at the ditch that is along the levee toe. Fall 2016.

LM Start	1.86	Rating **	M	Issue No.	16
LM End	1.86	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.000975 °	39.000975 °
				-121.537779 °	-121.537779 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:46604					
DS_ID:18588					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Found					
UCIP Comments: Inlet burried. Good candidate for video inspection as pipe is corroded.					
FIELD_STRUCT_DESC: 18-inch CM drain pipe through the levee, 14.5 feet below the crown. Flap gate on the waterward end. Concrete "U" headwall on the waterward side. Originally included in O+M manual (1955).					
FS Date: 9/11/2015 9:36:14 AM					

Photo 1 of 2 : UCIP_FA_2016_46604_54249.jpg



Drainage outlet on WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Interceptor Canal	Left	4.19	11/01/2016 11/01/2016	Sterling York

LM Start	1.86	Rating **	M	Issue No.	16 (cont)	
LM End	1.86	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			39.000975 °	39.000975 °	
				-121.537779 °	-121.537779 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:46604						
DS_ID:18588						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Found						
UCIP Comments: Inlet burried. Good candidate for video inspection as pipe is corroded.						
FIELD_STRUCT_DESC: 18-inch CM drain pipe through the levee, 14.5 feet below the crown. Flap gate on the waterward end. Concrete "U" headwall on the waterward side. Originally included in O+M manual (1955).						
FS Date: 9/11/2015 9:36:14 AM						

Photo 2 of 2 : UCIP_FA_2016_46604_54248.jpg



Debris covered inlet on LS toe.

LM Start	2.04	Rating **	M	Issue No.	15
LM End	2.04	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.003643 °	39.003643 °
				-121.538292 °	-121.538292 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:46603 DS_ID:18587 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Erosion at outlet may or may not be an issue. FIELD_STRUCT_DESC: 18-inch CM drain pipe through the levee, 14.5 feet below the crown. Flap gate on the waterward end. Concrete "U" headwall on the waterward side. PVC weir on inlet. Originally included in O+M manual (1955). FS Date: 9/11/2015 9:34:58 AM					

Photo 1 of 2 : UCIP_FA_2016_46603_54252.jpg



Concrete U-shaped outlet on WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Interceptor Canal	Left	4.19	11/01/2016 11/01/2016	Sterling York

LM Start	2.04	Rating **	M	Issue No.	15 (cont)
LM End	2.04	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.003643 °	39.003643 °
				-121.538292 °	-121.538292 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:46603 DS_ID:18587 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Erosion at outlet may or may not be an issue. FIELD_STRUCT_DESC: 18-inch CM drain pipe through the levee, 14.5 feet below the crown. Flap gate on the waterward end. Concrete "U" headwall on the waterward side. PVC weir on inlet. Originally included in O+M manual (1955). FS Date: 9/11/2015 9:34:58 AM					


Photo 2 of 2 : UCIP_FA_2016_46603_54251.jpg



Inlet with PVC weir on LS toe.

LM Start	2.11	Rating **	M	Issue No.	9
LM End	3.07	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.004562 °	39.015593 °
				-121.538482 °	-121.528533 °
DWR ID	DWR_RD0784_05_s_2012_9				
Comment Code					
DT : Ditch					
Inspector Comment					
Ditch at toe of slope. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_182_9_20161103_00025.jpg



View of landside looking downstream at the ditch that is along the levee toe. Fall 2016.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Interceptor Canal	Left	4.19	11/01/2016 11/01/2016	Sterling York

LM Start	2.47	Rating **	U	Issue No.	18
LM End	2.47	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.008994 °	39.008994 °
				-121.535679 °	-121.535679 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:50167

DS_ID:18597

EP_NO: N/A

Repair Type: Urgent

Crossing Status: Found

UCIP Comments: 7/29/2016 - Erosion scarp on LS cut into levee shoulder starting at inlet headwall. Cavity failure on WS shoulder approximately 2-feet in diameter and several feet in depth. (T. Hatch/UCIP)11/01/2015 - The concrete box weir structure on the landside inlet has slumped off the end of the pipe. DWR Chief inspector George Willie inspected the site on 8/13/2015 with Steve Fordice, General Manager of RD784. (P. Meagher - RD784)

2/27/2013 - Heavy erosion around inlet headwall due to beaver activity. (W. Wylie/UCIP)

FIELD_STRUCT_DESC: 18-inch corrugated metal drainage pipe through the levee, 15.5 feet below the crown. Flap gate on the waterside (WS) toe. Concrete "U" headwall located at the WS toe. (removable standpipe and bulkheads approved under Permit No. 9230, 1974 - Frach, Inc.). [Additional Reference(s): DWR Levee Logs, 2005. USACE Sacramento O&M Manual 145, August 1955 (Station 13+72). USACE As-built Drawings 2-4-106, Sheet 6, July 1944 (Station 13+72)]. FS Date: 7/29/2016 11:20:00 AM

LM Start	2.47	Rating **	U	Issue No.	18 (cont)
LM End	2.47	Issue Type +	En	Location *	LS

Photo 1 of 2 : UCIP_FA_2016_50167_54256.jpg



Outlet on WS.

Photo 2 of 2 : UCIP_FA_2016_50167_54255.jpg



Inlet on LS.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Interceptor Canal	Left	4.19	11/01/2016 11/01/2016	Sterling York

LM Start	2.51	Rating **	M	Issue No.	5
LM End	3.10	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.009463 °	39.015978 °
				-121.535200 °	-121.528173 °
DWR ID	DWR_RD0784_05_s_2013_5				
Comment Code					
FE : Fence					
Inspector Comment					
Fence along levee toe. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_182_5_20161103_00031.jpg



View of fence along the landside toe looking downstream. Fall 2016.

LM Start	3.06	Rating **	M	Issue No.	14
LM End	3.06	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.015549 °	39.015549 °
				-121.528590 °	-121.528590 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:46601 DS_ID:18596 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Pipe has been sliplined with PVC, but the liner appears to be eroding at outlet and may be disjointed internal to the levee. See pic. Good candidate for video inspection. FIELD_STRUCT_DESC: 12-inch CM drain pipe through the levee, 12.0 feet below the crown. Flap gate and concrete "U" headwall on the waterward side. PVC weir on inlet at LS toe. Originally included in O+M manual (1955). FS Date: 9/11/2015 9:26:56 AM					

Photo 1 of 2 : UCIP_FA_2016_46601_54261.jpg



Concrete U-shaped headwall on WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Interceptor Canal	Left	4.19	11/01/2016 11/01/2016	Sterling York

LM Start	3.06	Rating **	M	Issue No.	14 (cont)	
LM End	3.06	Issue Type +	En	Location *	LS	
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP Field Study			39.015549 °		39.015549 °
				-121.528590 °		-121.528590 °
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:46601 DS_ID:18596 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: Pipe has been sliplined with PVC, but the liner appears to be eroding at outlet and may be disjointed internal to the levee. See pic. Good candidate for video inspection. FIELD_STRUCT_DESC: 12-inch CM drain pipe through the levee, 12.0 feet below the crown. Flap gate and concrete "U" headwall on the waterward side. PVC weir on inlet at LS toe. Originally included in O+M manual (1955). FS Date: 9/11/2015 9:26:56 AM						

Photo 2 of 2 : UCIP_FA_2016_46601_54260.jpg



PVC weir on LS toe. Notice pipe debris from repair.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Interceptor Canal	Left	4.19	11/01/2016 11/01/2016	Sterling York

LM Start	3.96	Rating **	M	Issue No.	17
LM End	3.96	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.019787 °	39.019787 °
				-121.513386 °	-121.513386 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:50676
DS_ID:18593
EP_NO: N/A
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: 11/14/2016 - Photos added of exposed flap gate on WS and possible inlet location on LS. Condition remains as Non-Urgent because of inlet not being fully operable. Unknown if pipe will operate as designed during high water or if it is full of sediment. 11/01/2015 - Waterside Flap Gate Uncovered. Photo sent to DWR Matt Hoffman on 3/3/2014. Fresh photo sent to DWR Pavel Kazi on 9/9/2015. Landside toe has never been able to be located. Requesting DWR inspector to change the status of this issue to "No Action Needed". (P.Meagher - RD784). Pipe buried on LS toe and flap gate is blocked by soil on WS toe. (W. Wylie - UCIP Inspector).
FIELD_STRUCT_DESC: 18-inch CM pipe through the levee, 10.0 feet below the crown. Flap gate on the waterward end. Originally included in O+M manual (1955).
FS Date: 10/9/2015

LM Start	3.96	Rating **	M	Issue No.	17 (cont)
LM End	3.96	Issue Type +	En	Location *	LS

Photo 1 of 2 : UCIP_FA_2016_50676_56705.jpg



Outlet on WS toe .

Photo 2 of 2 : UCIP_FA_2016_50676_56704.jpg



Flap gate buried in soil at outlet on WS toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	--	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2016 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway			Bank	Unit Miles
Unit No. 06 South Dry Creek			Right	0.25
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/23/2016 - 3/23/2016		11/1/2016 - 11/1/2016	
DWR Inspector	Sterling York		Sterling York	
Accompanied By	Patrick Meagher RD 784		Patrick Meagher RD 784	

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

Reclamation District No. 0784 Plumas Lake

View of waterside looking upstream at well maintained annual vegetation. Fall 2016.

Page 1 of 2

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 06 South Dry Creek	Right	0.25	11/01/2016 11/01/2016	Sterling York

LM Start	0.06	Rating **	M	Issue No.	4
LM End	0.06	Issue Type +	En	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			38.985999 °	38.985999 °
				-121.509618 °	-121.509618 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:46776 DS_ID:18626 EP_NO: N/A Repair Type: Non-Urgent Crossing Status: Found UCIP Comments: 10-30-2015 - Waterside flap gate was cleared in December 2014 and again in September 2015 No LMA access available on Landside (P. Meagher).Pipe partially blocked on LS and flap gate blocked on WS (W. Wylie-UCIP Inspector) FIELD_STRUCT_DESC: 18-inch CM drain pipe through the levee19-feet below the crown. Gate valve on waterward side. Originally included in O+M Manual (1955). See Dwg. 2-4-106 Sheet 2. FS Date: 9/11/2015					

Photo 1 of 2 : UCIP_FA_2016_46776_54267.jpg



INlet at LS toe.

LM Start	0.06	Rating **	M	Issue No.	4 (cont)
LM End	0.06	Issue Type +	En	Location *	WS

Photo 2 of 2 : UCIP_FA_2016_46776_54266.jpg



Outlet at WS stream bank.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2016 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway			Bank	Unit Miles
Unit No. 07 Yuba River			Left	3.82
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/22/2016 - 3/22/2016		11/1/2016 - 11/1/2016	
DWR Inspector	Sterling York		Sterling York	
Accompanied By	Patrick Meagher RD 784		Patrick Meagher RD 784	

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 07 Yuba River	Left	3.82	11/01/2016 11/01/2016	Sterling York

LM Start	0.12	Rating **	A	Issue No.	2
LM End	3.81	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.135137 °	39.165505 °
				-121.550129 °	-121.495615 °
DWR ID	DWR_RD0784_07_f_2016_2				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_184_2_20161103_00005.jpg



View of landside looking downstream of landside well maintained annual vegetation. Fall 2016.

LM Start	0.12	Rating **	A	Issue No.	3
LM End	3.81	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.135138 °	39.165505 °
				-121.550129 °	-121.495615 °
DWR ID	DWR_RD0784_07_f_2016_3				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Well maintained annual vegetation. Fall 2016.					

Photo 1 of 1 : FA_2016_RD0784_184_3_20161103_00004.jpg



View of waterside looking downstream at well maintained annual vegetation. Fall 2016.

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2016 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway			Bank	Unit Miles
Unit No. 08 Three Rivers			Right	1.93
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/22/2016 - 3/22/2016		11/1/2016 - 11/1/2016	
DWR Inspector	Sterling York		Sterling York	
Accompanied By	Patrick Meagher RD 784		Patrick Meagher RD 784	

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

Reclamation District No. 0784 Plumas Lake

View of landside looking upstream of landside well maintained annual vegetation. Fall 2016.

Page 1 of 1

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2016 Levee Inspection Results

Reclamation District No. 0784 Plumas Lake

Waterway			Bank	Unit Miles
Unit No. 09 Feather River			Left	5.71
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	3/22/2016 - 3/22/2016		11/1/2016 - 11/1/2016	
DWR Inspector	Sterling York		Sterling York	
Accompanied By	Patrick Meagher RD 784		Patrick Meagher RD 784	

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

Reclamation District No. 0784 Plumas Lake

View of landside looking downstream of landside well maintained annual vegetation. Fall 2016.

Page 1 of 3

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 09 Feather River	Left	5.71	11/01/2016 11/01/2016	Sterling York

LM Start	4.97	Rating **	M	Issue No.	6
LM End	4.97	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.020167 °	39.020167 °
				-121.583516 °	-121.583516 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:46591					
DS_ID:23976					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Indicator Found					
UCIP Comments: Need to determine Permit for crossing.					
FIELD_STRUCT_DESC: 24-inch storm drain discharge pipe through the levee at unknown depth below the crown. Pumping plant on Landward toe. Pump Station No. 3. Paddle markers on both WS toe and LS toe at pumping plant fence.					
FS Date: 9/11/2015 9:04:50 AM					

LM Start	4.97	Rating **	M	Issue No.	6 (cont)
LM End	4.97	Issue Type +	En	Location *	LS

Photo 1 of 2 : UCIP_FA_2016_46591_27163.jpg



Paddle marker on WS toe.

Photo 2 of 2 : UCIP_FA_2016_46591_27162.jpg



Paddle marker on LS toe at pumping plant fence.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2016

Reclamation District No. 0784 Plumas Lake

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 09 Feather River	Left	5.71	11/01/2016 11/01/2016	Sterling York

LM Start	5.64	Rating **	M	Issue No.	5
LM End	5.64	Issue Type +	En	Location *	LS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			39.011146 °	39.011146 °
				-121.579794 °	-121.579794 °
DWR ID					

Comment Code

Inspector Comment

FS_ID:46586
DS_ID:23996
EP_NO: N/A
Repair Type: Non-Urgent
Crossing Status: Found
UCIP Comments: Need to determine Permit for Crossing.
FIELD_STRUCT_DESC: 2-Christy boxes. One on either side of crown.
Likely an electrical or other small conduit crossing.
FS Date: 9/11/2015 9:00:50 AM

LM Start	5.64	Rating **	M	Issue No.	5 (cont)
LM End	5.64	Issue Type +	En	Location *	LS

Photo 1 of 2 : UCIP_FA_2016_46586_27161.jpg



Christy box on WS shoulder.

Photo 2 of 2 : UCIP_FA_2016_46586_27160.jpg



Christy box on LS shoulder.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---